

11 PIN VEHICLE HEADLIGHT ADAPTER CHART

	VEHICLE	SYSTEM TYPE	CONFIGURATION	HEADLIGHT/BULB	PART NO.
CHEVY/GMC	1980 - 2006 Chevy/GMC	2 Lamp Rectangular Sealed Beam		6052 or H6054 (2B)	NONE REQUIRED
	1980 & Older Chevy/GMC	2 Lamp Round Sealed Beam		6014 or H6017 (2B)	NONE REQUIRED
	1987 & Older Chevy/GMC	4 Lamp Sealed Beam		High Beam 4651 or H4651 (1A) Low Beam 4652 or H4656 (2A)	MSC03444
	1988-1989 Chevy/GMC	4 Lamp Sealed Beam		High Beam H4701 (LF) Low Beam H4703 (UF)	MSC03446
	1990 - 2000 Chevy/GMC (Classic Body Style)	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam 9006 (HB4)	MSC03448
	1999 - 2002 Chevy/GMC (New Body Style)	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam 9006 (HB4)	MSC04292
	2003 - 2006 Chevy/GMC	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam 9006 (HB4)	MSC03448
	2007 Chevy/GMC (Classic Body Style)	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam 9006 (HB4)	MSC03448
	2007-Newer Chevy/GMC	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam (H11)	NOT AVAILABLE*
	2007-Newer Chevy/GMC	2 Lamp Sealed Beam		6052 or H6054 (2B)	NOT AVAILABLE*
	2003 - 2008 C4500/C5500	2 Lamp Sealed Beam		6052 or H6054 (2B)	NONE REQUIRED
	2004 - 2008 Colorado/Canyon	4 Lamp Replaceable Bulb		High Beam 9005 Low Beam 9006	MSC03448
	FORD	1980-1986 Ford	2 Lamp Sealed Beam		H6054 (2B)
1987-1991 Ford		2 Lamp Replaceable Bulb		9004 (HB1)	MSC03445
1992 - 2003 F150		2 Lamp Replaceable Bulb		9007 (HB5)	MSC03449
2004 - 2008 F150		2 Lamp Replaceable Bulb		9008 (H13)	MSC05652
1998 - 2008 Ranger		2 Lamp Replaceable Bulb		9007 (HB5)	MSC03449
1992 - 2004 Super Duty		2 Lamp Replaceable Bulb		9007 (HB5)	MSC03449
1999 - 2007 Super Duty		2 Lamp Sealed Beam		H6054 (2B)	NONE REQUIRED
2005 - 2007 Super Duty		2 Lamp Replaceable Bulb		9008 (H13)	MSC05652
2008-Newer Super Duty		2 Lamp Replaceable Bulb		9008 (H13)	NOT AVAILABLE*
DODGE		1991-1993 Dodge Ram	2 Lamp Sealed Beam		6052 or H6054 (2B)
	1994 - 1998 Dodge Ram	2 Lamp Replaceable Bulb		9004 (HB1)	MSC03445
	2000 - 2004 Dakota, 2000- 2003 Durango	2 Lamp Replaceable Bulb		9007 (HB5)	MSC03449
	1999 - 2001 Ram 1/2 Ton (Without Sport Package)	2 Lamp Replaceable Bulb		9004 (HB1)	MSC04287
	1999 - 2001 Ram 1/2 Ton (With Sport Package)	4 Lamp Replaceable Bulb		9004 / 9007 (HB1/HB5)	MSC04291
	1999 - 2002 Ram 3/4 & 1 Ton (Without Sport Package)	2 Lamp Replaceable Bulb		9004 (HB1)	MSC04287
	1999 - 2002 Ram 3/4 & 1 Ton (With Sport Package)	4 Lamp Replaceable Bulb		9004 / 9007 (HB1/HB5)	MSC04291
	2002 -Newer Ram 1/2 Ton	2 Lamp Replaceable Bulb		9007 (HB5)	NOT AVAILABLE*
	2003 - Newer Ram 3/4 & 1 Ton	2 Lamp Replaceable Bulb		9007 (HB5)	NOT AVAILABLE*
	2006 - Newer Ram 1/2, 3/4, & 1 Ton	2 Lamp Replaceable Bulb		9008 (H13)	NOT AVAILABLE*
JEEP	1997-2002 Jeep Wrangler	2 Lamp Sealed Beam		H6024	NONE REQUIRED
MITS	1999 - 2004 Mitsubishi FG (4X4)	4 Lamp Replaceable Bulb		46H3 / 46R3 (1A/2A)	NONE REQUIRED
	2005 - Newer Mitsubishi FG (4X4)	2 Lamp Replaceable Bulb		9003 (H4)	NOT AVAILABLE*
NISSAN	2004 - Newer Titan	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam 9006 (HB4)	NOT AVAILABLE*
TOYOTA	2000 - Newer Tundra	2 Lamp Replaceable Bulb		9003 (H4)	NOT AVAILABLE*

* 13-Pin Harness must be used on this vehicle. Refer to 13-Pin Vehicle Headlight Adapter Chart to see if Headlight Adapters are required.