



# SERVICE BULLETIN NO. 179

## BlockerBeam

### 2001 Ford Superduty


### Ford F-250 / F-350/ F-450/ F-550 Trucks

November, 2000

Reports from the field have indicated that Ford Motor Company has incorporated a metal cross member below the front bumper on the 2001 Model Year Super Duty Vehicles. This metal cross member is called a "**BlockerBeam**". The actual incorporation date is October, 2000.

To install a Meyer Snowplow onto these vehicles you must first remove the BlockerBeam. The BlockerBeam and hardware should be retained.

**Warning:** Removal of the BlockerBeam without the installation of the snowplow attachment hardware may effect air bag deployment in a crash. Do not operate the truck unless either the BlockerBeam or snowplow attachment hardware is installed on the vehicle.



Meyer Products assumes no responsibility for installations not made according to these instructions

Meyer Products reserves the right, under its continuing product improvement program, to change construction or design details, specifications and prices without notice or without incurring any obligation.

Meyer Products  
18513 Euclid Ave. • Cleveland, Ohio 44112-1084  
Phone 486-1313 (Area Code 216)  
email warranty@meyerproducts.com  
www.meyerproducts.com

Diamond Equipment  
6 Angell Lane • Damariscotta, ME 04543-9720  
Phone 563-2227 (Area Code 207)  
email info@diamondplow.com  
www.diamondplow.com

Printed in U.S.A. © 2000

